Exhibit 1

12308	CN	Undated	Brochure (attached to claim form)		100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	3/26/03	claim form)	Letter/Report from Pinchin Environmental to Toronto District School Board re: identification of fireproofing as MK-3	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	8/10/81	Report	Sampling of Materials Suspected to Contain Asbestos Carried Out at Humberside Collegiate Institute by Trevor Harris & Associates	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	1982	Report	The Toronto Board of Education - Asbestos Removal - 1982 (II)	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	9/16/85	Report	Site Inspection of Asbestos Removal from Humberside Collegiate Institute by D.J. Pinchin Technical Consulting Ltd.	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	9/10/90	Letter/Report	Letter/Report from Pinchin to Toronto Board of Education re: Airborne Asbestos Measurements - Humberside Collegiate Institute - Pinchin Report No. 1722-515	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	2/00/04	Report	Asbestos Abatement - Glove Bag Method - Humberside Collegiate Institute - 2nd Floor Fan Room	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	2/2/04	Invoice	Invoice from Pinchin Environmental to TDSB - Humberside C.I., 2nd Floor Fan Room, Asbestos Consulting - \$1,460.55	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	Undated	Drawings	Floor Plans - Humberside Collegiate Institute	100 Oak Street Hampton, SC	Speights & Runyan
12308	CN	Undated	Photos	Photos - Humberside Collegiate Institute	100 Oak Street Hampton, SC	Speights & Runyan